


2.1.1



Axes and Axis directions

1. tool is behind spindle centre line



DIN 66217

2. tool is in front of spindle centre line



For both systems:

The **larger** the diameter, the **greater** the x value.


The **longer** the length, the **greater** the z value.

2.1.2

Reference points in the working area

The most important reference points are:

-  **M** Machine zero point
-  **R** Reference point
-  **T** Tool reference point




	X			Z			S	K	[mm]
	min	max	tra-verse	min	max	tra-verse	max		
CT40	275	535	260	183,5	823,5	640	900	10,5	

2.1.3

Component zero point

The component zero point (symbol ) is the reference point for the geometried data included in the programme.


1. Component zero point on the face



	X	Z
P ₀	0	0
P ₁	35	0
P ₂	56	-20
P ₃	80	-50

This zero point position is more favourable for programming.

2. Component zero point on the contact surface (base of jaws)




	X	Z
P ₀	0	80
P ₁	35	80
P ₂	56	60
P ₃	80	30

2.1.4


Reference dimension input (G90 Absolute)

Absolute dimensions always relate to the **component zero point** (hence reference dimension)



Actual position: X40 Z0

input: X50 Z - 40 = **Target** position




G90* indicates the tool traverses

TO the given position

Actual position: X50 Z - 40

input: Z2 = **Target** position




Actual position: X50 Z2

* G90 = effective when stored

2.1.5

Chain dimension input (G91 incremental)

With incremental dimensional input, the component zero point is **NOT** used as reference. The programmed x and z values relate to the **LAST tool position**.




Actual position:* X40 Z0

Attention:
Radius value

input: X5 Z-40

START — Press
button



G91* indicates
the tool traverses


A GIVEN DISTANCE in the
direction defined.

Here: X5 mm, + direction
Z40 mm, - direction

Actual position: X50 Z-40

Input: Z42

START — Press
button




Actual position: X50 Z2

* Even if chain dimensions are programmed, the **actual position** (absolute dimension) appears on the screen after the traverse is completed.

Effect of tool nose radius


In order that the time the tip is in contact is not too short, the tip of roughing and finishing tools is rounded.




The tool tip radius varies between 0,4 and 1,6mm.

Theoretical tip of the tool
= **reference point for the control**


Effect when ...




Turning



Facing



Turning a taper



Turning a radius



* The larger the tool tip radius, the greater the surplus stock (i.e. in accuracy).

2.1.7


Tool nose compensation (T.N.R.C.)

The removal of inaccuracies which result on all contours which are not parallel to the axes, due to the tool nose radius, is called **compensation**.

This compensation is carried out **automatically** on CNC turning machines.





G0, G1, G2, G3; G41, G42, G40





G0

Rapid





G1

Linear feed





G2

Clockwise arc





G3

Counter-clockwise arc




G42

Tool traversing to the right of the contour looking in the feed direction



G41


Tool is to the left of the contour





G40

Cancels G41/G42



M3, M4, M5; M7, M8, M9; M30




M3
Spindle
clockwise




M4
Spindle
counter-clockwise





M5
Spindle stop





M7
1 Coolant ON




M8
2 Coolant ON





M9
Coolant OFF





M30
End of programme
+
Return to start of
programme



Material library



Tooling library



T = Tool number

WT = Tool type

FC = Colour

X = Setting dimension L (Radial value)

Z = Setting dimension Q

I = Position of the tool centre point in x direction

K = Position of the tool centre point in z direction

A = Setting angle κ

B = Included angle ϵ

D = Diameter of tool


L = Useable length of the tool

Cutting speed and spindle speed

1.




= constant cutting speed in $\frac{m}{min}$



2.



= constant spindle speed in $\frac{1}{min}$




2.4.4

Performance curves of a CNC turning machine

CT 40:



$$n_{\min} = 20 \frac{1}{\text{min}}$$

$$n_{\max} = 4000 \frac{1}{\text{min}}$$



Range I: $i_1 = 3,18:1$ (M41)*

Range II: $i_2 = 1:1$ (M42)



* M43 and M44 are further gear ranges on larger machines

— — — — — n [min⁻¹]

G26 S630 = Spindle speed limit

The GILDEMEISTER-EltroPilot control allows the contour to be displayed on the screen at any stage of programming.

This facility is of considerable advantage in **shop-floor programming**.

